	Type	#	Hits	Search Text	DBs	Time Stamp
<b>←</b>	BRS	L 1	554	(((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 stress) with (optic\$5 near2 (fiber or cable or waveguide or preform)) and @ad<=20021018	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23
2	BRS	L2	21008 0	polariz\$5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:45
m	BRS	Т3	36812	(rotat\$5 or turn\$5 or (fiber or waveguide cnear2 test) or dut or source or laser or em	USPAT; US-PGPUB; EPO; 3	2004/09/23 07:56
4	BRS	L4	554	(((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 stress) with (optic\$5 near2 (fiber or cable or waveguide or preform or (device near2 under near2 test) or dut))) and @ad<=20021018	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 07:56
5	BRS	L5	105	1 and 2 and 3	USPAT; US-PGPUB; EPO;   JPO; DERWENT; IBM_TDB	2004/09/23 07:57
9	BRS	T e	34713	(rotat\$5 or turn\$5) near8 (fiber or waveguide or (device near2 under near2 test) or dut or cable or preform or source or laser or emitter or emitting)	•• a	
7	BRS	L7	102	1 and 2 and 6		2004/09/23 08:02
ω	BRS	L8	10626 9	phase near2 shift		2004/09/23 08:02
<u></u>	BRS	179	25	7 and 8	USPAT; US-PGPUB; EPO;   JPO; DERWENT; IBM_TDB	2004/09/23 08:02
10	BRS	L10	32	(((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 (residual near2 stress)) with (optic\$5 near2 (fiber or cable or waveguide or preform))) and @ad<=20021018	; US-PGPUB; EPO; DERWENT; IBM_TDB	2004/09/23 09:17
11	BRS	L11	2	8 and 10	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:17
12	BRS	L12	18448	(rotat\$5) near8 (fiber or waveguide or (device near2 under near2 test) or dut or cable or preform or source or laser or emitter or emitting)	USPAT; US-PGPUB; EPO; ; JPO; DERWENT; IBM_TDB	2004/09/23 09:19

	Туре	#	Type L # Hits	Search Text	DBs	Time Stamp
13	13 BRS	L13 18	18	10 and 12	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:44
14	14 BRS	L15	74897	L15 74897polariz\$5 near3 (light or beam)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:45
15	15 BRS	L14	Н	(((determin\$5 or detect\$5 or measur\$5 or inspect\$5 or monitor\$5 or calculat\$5) near8 (circular near2 stress)) with (optic\$5 near2 (fiber or cable or waveguide or preform))) and @ad<=20021018	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23
16	16 BRS	L16	2	(circular near2 stress\$3) with (phase near2 shift\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/09/23 09:46
17	17 BRS	L17	П	1 and 16	USPAT; US-PGPUB; EPO; 2004/09/23 JPO; DERWENT; IBM_TDB 09:46	2004/09/23 09:46